Reccomended Spare/Replacement Parts for Your Machine

Customer Name	Lockheed Martin
Job Number	FC-24-21429-5
Part Name	Rivet

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system

FCI Part Number	Description	Quantity on Machine Shipped	Notes
Drive Unit Parts			
E-0379	E Series Vibratory Coil for Drive Unit	2	
SP-21-38	3/8" Springs for 21" Drive Unit	8	
#24	Rubber Isolation Feet for Drive Unit	4	
Controls and Sensors			
121-000-2000	Rodix FC-200 Feeder Cube for Bowl	1	
FU-R77TZ	Keyence Thru-Beam Sensor	1	
FS-N41C	Keyence Main Unit Amplifier	1	
OP73864	Keyence Cordset for Amplifier	1	
Pneumatics			
AR30-N02E-Z-D	SMC Air Filter / Regulator	1	
PCM10-125-02B	2 Port Air Outlet Manifold	1	
MIW12-12D2A	Two Finger Toggle	1	

FCI100	SS Airjet Assembly	1
Other		
FC-24-21429-5-TVA	Track to Venturi Adapter	1
FC-24-21429-5-VENT	Venturi	1
FC-24-21429-5-VTA	Venturi to Flexible Tube Adapter	1
FC-24-21429-5-DF	Discharge Finger for Toggle	1
FC-24-21429-5-HF	Holdback Finger for Toggle	1