Reccomended Spare/Replacement Parts for Your Machine

Customer Name	Sussex IM Inc
Job Number	FC-25-21947
Part Name	Vessel

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system

FCI Part Number	Description	Quantity on Machine Shipped	Notes
Bowl 1 Drive Unit			
E-0379	E Series Vibratory Coil for Drive Unit	2	
SP-30-316	3/16" Steel Springs for 30" Drive Unit	24	
#24	Rubber Isolation Feet for Base Drive	4	
Bowl 2 Drive Unit			
E-0379	E Series Vibratory Coil for Drive Unit	2	
SP-30-316	3/16" Steel Springs for 30" Drive Unit	23	
#24	Rubber Isolation Feet for Base Drive	4	
Prefeed Conveyor Parts	**SN: 414081**		**Pulley Assemblies Available upon Request**
U1-14-036	Replacement Belt for 14 x 36 Conveyor, U1 Style White Urethane	1	
30-7310C	Idler Pulley Assembly. Includes Pulleys, Bearings, Adapters, and Screws	1	
LP 40-7410-RC-SM5M	Drive Pulley Assembly. Includes Pulley, Bearings, Fiber Washers, and Set Screws	1	
BLM460SHP-GFV	Oriental Motor Brushless DC Motor	1	
GFV-4G100AS	100:1 Gearhead for Motor	1	

CC040KHBLF	Oriental Motor 4M Cable for Motor to Driver	1	
Diverting Conveyor Parts	**SN: 414082**		**Pulley Assemblies Available upon Request**
U1-08-044	Replacement Belt for 8 x 44 Conveyor, U1 Style White Urethane	1	
30-7308C	Idler Pulley Assembly. Includes Pulleys, Bearings, Adapters, and Screws	1	
40-7408-RC-SM5M	Drive Pulley Assembly. Includes Pulley, Bearings, Fiber Washers, and Set Screws	1	
BLM460SHP-GFV	Oriental Motor Brushless DC Motor	1	
GFV-4G100AS	100:1 Gearhead for Motor	1	
CC040KHBLF	Oriental Motor 4M Cable for Motor to Driver	1	
Control Components			
121-000-2005	Rodix FC-205 Plus Controller for Bowls	2	
BLE2D60-A	Oriental Motor Driver for Conveyors	2	
B1N1C3	Noark Electric 3A Circuit Breaker	2	
1122750000	Weidmuller Relay, 12VDC 1CO	2	
1122770000	Weidmuller Relay, 24VDC 1CO	1	
EX9IL2N3	Noark Electric Green Pilot Light	1	
ZS3EV733-IP65	Baco 25A Main Disconnect	1	
Sensors and Cables			
Q4XTBLAF500Q8	Banner Q4X Laser Sensor	3	
RKT4-225/5M	Lumberg Cordset for Q4X	3	
Other			
M100-34-6	Machine Leveling Feet	4	